

Storm Sewer
Daylight point
(Lubber Run)
Inspection with photos
by ECC on 4/4/13

Approx location of SWM Vault #4